



DIRECT REPLACEMENTS

Replace existing position indicators with C.E. Replacement Series



ME110-XX
IEE Light Bulb Replacement



DB310-XM
Dover Light Bulb Replacement



MR105-XXX
Otis Roto Dial Replacement

When the need occurs to replace existing position indicators, look to CE first. CE has adapted many of today's answers to yesterday's products. Within the CE Direct Replacement line, old rotary mechanical PI's can be replaced with digital LED style position indicators. This solution can run off of existing travel cable wiring with signals from the existing controllers. The replacement can be bolted to the same stud pattern and be hooked up using the same wiring. When the need arrives to replace an existing PI, call CE with your requirements. Custom units are not a problem at CE. We look forward to helping you solve your problems.

Find what fits for you and consult the factory if you have a need for a particular replacement.



C.E. Electronics Inc.
ask for the extraordinary